



EMC INTEGRITY

DO NOT DRILL HOLES IN THE BOX.
TERMINATE ALL CABLES OUTSIDE BOX.


OUTPUTS & INPUTS




PRESSURE TRANS



COMMS



TEMP SENSORS



CONNECTIONS FOR USE WITH CP4H & CPST

THIS IS AN UNCONTROLLED COPY – UNLESS STAMPED WITH CONTROLLED COPY STAMP

DOC 01888 ISS 3 Feb 1999