



EMC INTEGRITY
DO NOT DRILL HOLES IN THE BOX.
TERMINATE ALL CABLES OUTSIDE BOX.


OUTPUTS &
INPUTS




PRESSURE TRANS



COMMS



TEMP SENSORS



CONNECTIONS FOR USE WITH CP4C

THIS IS AN UNCONTROLLED COPY - UNLESS STAMPED WITH CONTROLLED COPY STAMP

DOC 01896 ISS 2 Mar 1997