

| JTL FIRMWARE VARIATIONS | | RL310 |
|--------------------------------|---|--------------|
| VERSION | DESCRIPTION | DATE |
| v0.4.1305 | Original issue. | Apr 2019 |
| v1.4.1305 | Corrections to channel data dependencies. Correction to Honeywell status data on the maintenance unit. | May 2019 |
| v2.4.1305 | Alarm levels allowed to be set to 0. Corrections to MU code to allow honeywell status of inhibited and no data available to be displayed. | May 2019 |
| v3.4.1305 | Modbus protocol changed to 2 stop bits. | July 2019 |
| v4.4.1305 | Jnet communications error on channels 9-31 corrected. | Aug 2019 |
| v5.4.1305 | Alarm level items moved up by 1 to prevent spurious alarms when channels 29 & 30 are enabled. Misaligned channel alarm error corrected. Channel inhibited added to alarms. Honeywell RATE, STEL & LTEL alarms added. | Apr 2020 |
| v6.4.1305 | Honeywell no data available sets equipment fault. | Apr 2020 |