EMC INTEGRITY
DO NOT DRILL HOLES IN THE BOX.
TERMINATE ALL CABLES OUTSIDE BOX.



CONNECTIONS FOR USE WITH CP4L

THIS IS AN UNCONTROLLED COPY – UNLESS STAMPED WITH CONTROLLED COPY STAMP