

JTL FIRMWARE VARIATIONS		LCPL
VERSION	DESCRIPTION	DATE
v0.00.0	Original issue based on LCIL v02 which was withdrawn due to legacy conflicts on the network communications. Separate minimum superheat and minimum valve opening added for 2 temperature control on items 186 & 187.	Nov 2000
v0.00.1	Network communications for item 75 corrected to maintain legacy issues with previous models.	Jan 2001
v0.00.2	Learned defrost correctly activated in event of plant communications fail. Learned defrosts problem at midnight corrected. Error where first learned defrost is ignored corrected. Learned defrost saved correctly through a power down of controller.	Feb 2001
v0.00.3	Plant data information added on items 211 - 217 for use with Mark 2 optimisers and defrost scheduling. Additional factory information added. Fans only display changed to OFF on LCD8/9 displays. Broadcast "receiving" of site wide data added. Backup defrost activated alarm added. Mark 2 pcb supported. Communications fixed at 2 wire.	Feb 2003