

<b>JTL FIRMWARE VARIATIONS</b>		<b>IF31</b>
<b>VERSION</b>	<b>DESCRIPTION</b>	<b>DATE</b>
v1.00.0	Original issue.	Nov 2009
v1.00.1	Migrate to PIC16F886 using internal 8MHz oscillator	Jan 2011
v1.00.2	Add non-minimum value default capability for items. Add text support to MU for choosers. Add bit pattern data type for visual representation of inputs and outputs on MU EE memory handling enhanced.	June 2013
v1.00.3	Addition of Modbus RTU protocol. Correction on Modbus ASCII protocol to report type/subtype information correctly	June 2013
v1.00.4	Improve Modbus handlers to report exception codes properly. Code 3 (Illegal Data Value) now used. Code 1 (Illegal Function) is used when MU in use and attempt is made via serial port to set a non-volatile (EE stored) item. Parity error detection corrected in Modbus RTU protocol.	Nov 2013