

JTL FIRMWARE VARIATIONS		FL210
VERSION	DESCRIPTION	DATE
v1.00.0	Original issue.	Mar 2015
V0.00.1	Sensor selection errors corrected. Pump speed voltage input facility added. Temperature setpoint and mode added to logged data.	Apr 2015
V0.00.2 & V2.2.787	Dependency error corrected on pack 2 2 water return and tank 2 temperatures which were affected by pack 1 refrigerant gas temperature when they were faulty. Phoenix 2 version available.	Dec 2015
V3.3.830	Start of time moved to Jan 1 st 2016 Phoenix code enhanced to Phoenix 3 for Jnet use. Phoenix and PIC data added on comms and Maintenance unit. Modbus comms delay timers added. Modbus communications suspended during parameter setup. Modbus retry timer included when there is a modbus error reply. Heat harvester choice added on item 41. Plant zone operation at 38.4kb added. Interface modules can be disabled by setting device numbers to 0. Download parameters operation corrected.	Mar 2017
V4.3.830	Corrections to interface sensor fault handling to remove tank sensor fault and add missing sensor faults on heat exchangers. Misaligned faults on items 87 and 88 corrected for MU only.	Oct 2020