


PA510 WIRING DIAGRAM



- NOTES:**
1. Input states as follows:
 Closed contact = Input present
 Open contact = Input not present
 2. C4, C5, C6, C7 must have neutral connected to them, and their 'NO' and 'NC' terminals (marked*) are used for inputs as shown.



JTL SYSTEMS LTD
 41 KINGFISHER COURT, HAMBRIDGE RD,
 NEWBURY, BERKSHIRE: RG14 5SJ
 TEL: 01635 263646 FAX: 01635 263647

ISSUE	DESCRIPTION	APP'D	DATE
1	ORIGINAL ISSUE	JFH	10/08

TITLE:

PA510 WIRING

PROJ.	DRG No:	SHT	OF	ISS.
	03476	1	1	1

THIS IS AN UNCONTROLLED COPY - UNLESS STAMPED WITH CONTROLLED COPY STAMP