

JTL FIRMWARE VARIATIONS		LP160
VERSION	DESCRIPTION	DATE
v0.00.0	Original issue	May 2014
v0.00.1	Transducer fault corrected.	June 2014
v0.00.2	<p>Faulty compressor removes pressure healthy output.</p> <p>Low ambient temperature removes pressure healthy output.</p> <p>Broadcast timer function added which can remove pressure healthy output.</p> <p>Start address for PROM check sum redefined.</p> <p>End address for PROM checksum corrected.</p> <p>Special cases added for initial power up (1st minute) in both Phoenix and non Phoenix modes.</p> <p>Call to write NVRAM added on default write of unit nos and factory settings.</p> <p>Unsafe data timer initial value extended to 120 sec.</p> <p>Start time moved to Jan 1st 2016</p> <p>Phoenix capability added at Phoenix 3 level.</p> <p>Compressor restart pressure setpoint added.</p> <p>Site temperature and humidity added to MU items.</p>	May 2017