

<b>JTL FIRMWARE VARIATIONS</b>		<b>IF51</b>
<b>VERSION</b>	<b>DESCRIPTION</b>	<b>DATE</b>
v1.00.0	Original issue.	Sept 2013
v1.00.1	Report open and short circuits on alarm bytes 80 and 90	Dec 2013
v1.00.2	Extend PT1000 Range -80.0 to +125.0 C. Hardware change required.	Dec 2013