

JTL FIRMWARE VARIATIONS		UP110
VERSION	DESCRIPTION	DATE
v0.4.1134	Production release	Sept 2017
v1.4.1151	Text on item 393 corrected. Missing decimal point on item 392 added. PWM output changed to unload scroll compressor.	Mar 2018
v2.4.1214	Discharge pressure shutdown error corrected. Some missing discharge pressure dependencies added.	Apr 2018
v3.4.1305	Suction pressure transducer fault error corrected. R448A error corrected. R448A & R449A use dew figures for discharge pressure operation. Read PIC system info operation changed.	Jan 2019