

JTL FIRMWARE VARIATIONS		FL330
VERSION	DESCRIPTION	DATE
v0.5.1094	Development issue	Jan 2019
V1.5.1194	Production release	May 2019
v2.5.1321	<p>Temperature filtering added to Phoenix. High and low sensor fault flags deglytched for Phoenix RT. Pump speed and flow operation corrected. Panel display vector changed to tank temperature. Some text changes on MU. Alarms completely realigned to work on items 80 and 90 only but to remain compatible with the FL2 products. Item 88 corrected to item 87. Pump speed and flow operation corrected. Low tank temperature alarm added. Common graphical display items added for digital I/O. Temperature reading filter value added on item 540. Display changed to tank temperature.</p>	Apr 2020
v3.5.1321	Changes to datalog items when working with legacy network controllers.	May 2020
v4.5.1382	<p>Plant healthy input assigned specifically as pump healthy. Pump fault alarm added with 5 minute timer. Plant fault alarm now only occurs when the Auto input is not present. Low tank temperature alarm continues to operate when there is a plant or pump fault. Pump enabled when heat harvester operation selected and activate heat reclaim input present. Heat calculation error corrected.</p>	July 2020