

JTL FIRMWARE VARIATIONS		UBPA
VERSION	DESCRIPTION	DATE
v0.5.1233	Development release	Aug 2019
v0.5.1265	Production release.	Sept 2019
v1.5.1294	Change to defrost co-ordination operation after power down to prevent unnecessary defrost requests. Item dependency code changed to avoid data glitches associated with Phoenix operation. Learned defrost data protected through power down. Network trim adjustment corrected.	Dec 2019